

v9.7.19–12/06/2017**Upgrading:**

Firmware upgrade path:

Current Firmware Version	Upgrade Path	Hardware	File
v9.4.x	Upgrade to v9.7: build #	<ul style="list-style-type: none"> xxx (PN1, PN2, PN3) xxx (PN4) 	FileName.bin
v9.5.x	Upgrade to v9.7: build #	<ul style="list-style-type: none"> xxx (PN1, PN2, PN3) xxx (PN4) 	FileName.bin
v9.6.x	Upgrade to v9.7: build #	<ul style="list-style-type: none"> xxx (PN1, PN2, PN3) xxx (PN4) 	FileName.bin
v9.7.x	Upgrade to v9.7: build #	<ul style="list-style-type: none"> xxx (PN1, PN2, PN3) xxx (PN4) 	FileName.bin

NOTE: Migrating the Database – Due to the extensive number of changes between v9.7 and previous versions, migrating an existing database into v9.7 is not supported.

Fixed in This Release

System Software: Survey	ABC-9844 In some cases after an upgrade, the system became slow and sluggish.
System Software: Survey	ABC-9841 The client crashed in the following case: While shooting, with a large number of shots in the collection queue, and entering comments.
System Software: Survey	ABC-9840 While shooting with a long line, the client crashed after deleting a xxx.
System Software: Survey	ABC-9831 The client crashed because the file-name.exe file was missing from the c:\path directory.

Table 4–1 Known Issues

ABC-4188 Firmware	Description – Xxxx fails if xxx is low. Workaround – Manually redeploy the xxx
ABC-4096, Firmware	Description – After a firmware upgrade, the xxx indicators reflect the results from the test performed prior to the firmware upgrade, and may not be correct. Workaround – Manually redeploy the xxx.
ABC-3882, System software: User Interface	Description – In some cases, clicking between windows causes the windows to become undocked. Workaround – Click more slowly and ensure that you are not clicking and dragging as that causes the window to undock.
ABC-3864, System software: Other	Description – The Equipment Table total row count does not recalculate when xxx. Workaround – Change any filtered column's filter then change it back. Or toggle the All Filters button and toggle back. The counts total will be updated.
ABC-3861, System software: Shot-Based Acquisition	Description – The xxx does not update when you change the roll until you select a different row. Workaround – None
ABC-3825, System software: Installation	Description – Server installer prompts twice for uninstalling the previous version. Workaround – Click Yes for both prompts. The install should progress normally.